



Zubehör / Accessories / Accessoires




Löttülle (Messing) /
Soldering tailpiece (brass) /
Douille à braser



Schweißtülle (Stahl) /
Welding tailpiece (steel) /
Douille à souder (acier)



Gewindetülle (Messing) /
External thread tailpiece (brass) /
Douille à filet




Entleerungs-Adapter /
Draining adapter /
Adaptateur de vidange




MU2H051GE25-1101
04.100.70.001.000


Montage / Installation / Montage




Einbaulage / Fitting position /
Position de montage



Alternative / Alternative /
Alternative




! Durchflußrichtung beachten / Observe flow direction/
Faire attention à voie d'écoulement





Montage- und Bedienungsanleitung /
Installation and operating instructions /
Mode d'emploi

Kombi-FC
V5015




MU2H051GE25-1101
04.100.70.001.000

Einstellen/Absperren / Setting/Shutoff /
Régler/Arrêter




Entleeren - nur im Rücklauf möglich / Draining - only possible in the return / Vidanger - seulement possible à retour


1




2




3




4



5



6



ROBINEX AG
SA